ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0360, W0645, W0641, W0629, W0649, W0651, W0681, W	NA, 4th Crs, 2nd Crs, 1st Crs, 1st Main Rd, Pattandur Agrah, R H B Colcny, 6th Crs, R H B Colcny, 7t	Akshayanagara, Chitra Layout Chikkadinne
Segment No.	**Total Length (m)**	
3/C-W0360/S034514	887.00	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	150.49	77.565434	13.101667	77.566818	13.101568	WO 649	END
2	130.65	77.565420	13.101657	77.565088	13.100528	WO 649	END
3	32.03	77.564798	13.100609	77.565082	13.100531	WO 629	END
4	111.57	77.564535	13.101043	77.564208	13.100087	WO 647	END
5	398.14	77.564916	13.101106	77.563800	13.097678	WO 645	END
6	64.12	77.563323	13.098221	77.563897	13.098086	WO 360	END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains at Akshayanagara, Chitra Layout Chikkadinne and other areas in ward No:03	11000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to roads and drains at Akshayanagara, Chitra Layout Chikkadinne and other areas in ward No:03	003-16-000033
Work Order No.	**Work Order Date**	**Period of Extention**
EE/YNK-D/EMT-05/WO/83/2017-18	30/06/2017	180 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/06/2017	29/06/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0360, W0645, W0641, W0629,

AE-03

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

warya infrastructure
opers Prop.
ndru

0.00

ne No.

E-Mail ID

22043376

Field Inspection Details

Number of Trees	Any Other Information	Name
30		chandrakanth raju
Date of Inspection	**Remarks**	
14/03/2018		

Category	Image	Photo Remark
Segment Start		This photo seems out of range
Segment Start		This photo seems out of range
Segment Start		This photo seems out of range
Segment Start		This photo seems out of range
Segment Start		This photo seems out of range
Segment Start		This photo seems out of range
Segment Start		This photo seems out of range
Segment Start		This photo seems out of range

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0360, W0645, W0641, W0629,

AE-03

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks					
Designation	Approver Name	Date	Target Date	Remark	

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಮಲ್ಲೇಶ್ವರಂ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

AE-03

Zone: YELAHANKA Ward No: 3 Ward Name: Alturu Street ID: W0360, W0645, W0641, W0629,